



# WINDSOR

30 OZ. DESIGNER STRIAE NYLON CARPET

## *Premium, long-lasting style and performance*

Create a comfortable and fashionable environment with Windsor Premium Sheet/Roll Goods. Easy on the eyes and strong enough to withstand the toughest of traffic levels, the Windsor collection has become the designer's favorite for commercial spaces.

- Naturally inspired beautiful striated design
- Tufted 30 oz. nylon provides superior performance, strength and comfort
- Available in carpet tile, sheet/roll goods and custom/logo matting, making it a highly versatile product



01. Dark Grey



02. Charcoal Black



03. Navy Blue



04. Taupe



05. Red

# WINDSOR

## PREMIUM NYLON SHEET/ROLL GOODS



### SUGGESTED USES

Office Environments, Airports, Conference Rooms, Lobbies, Libraries, Retail/Department Stores, Resorts, Restaurant Entryways, Spas, etc.

Construction:	Tufted 100% PA6 solution space dyed
Fiber:	100% solution-dyed UV stabilized ASOTA* polypropylene
Primary Backing (Roll Goods):	Premium Composite Rubber
Backing (Carpet Tile):	Premium (eco) Bitumen
Pile Height (± 0.5mm):	0.275"
Total Height (± 7.5%):	0.375"
Pile Weight (± 7.5%):	30 oz/sy
Total Weight (± 7.5%):	70 oz/sy
Sheet/Roll Width (± 2%):	6' 7" or 13' 2"
Also available in Carpet Tiles. See Spec Sheet for full details.	
Tile Size (± 2%):	19.69" x 19.69"

### LIMITED WARRANTY

Full Commercial Warranty 5 years  
 Summary of Warranty

Products must be professionally installed to validate the warranty. van Gelder, Inc. warrants Sheet/Roll Goods against wear for a period of 5 years in a commercial application. This warranty applies only to material that is properly installed and maintained, while being used as intended and recommended. If the defect is covered by this warranty and is reported to van Gelder, Inc. within the Warranty period, van Gelder, Inc. will supply new material of same or similar grade to repair or replace the defective material.

- **Wear**  
 Defined as complete removal of wear layer, pattern and color due to wear from normal traffic and maintenance. If the wear occurs within 5 years from date of purchase, van Gelder, Inc. will provide replacement materials or repair, of only the effected area.
- **Manufacturing Defects**
- van Gelder, Inc. warrants materials are free from manufacturing defects and will replace defective floor covering and reasonable installation costs for a period of up to one [1] year from date of purchase. van Gelder, Inc. will not pay labor costs to repair or replace materials that defects were apparent before or at the time of installation.
- **Other Limitations**
  - This warranty is non-transferable
  - Manufacturing defect must be reported within 3 months from date of purchase.
  - This Warranty covers only properly installed & maintained floors
  - van Gelder, Inc. excluded and will not pay for any consequential or incidental expenses.
  - van Gelder, Inc. reserves the right of final judgment and may refuse claims in certain instances.

*\*For a copy of the full warranty please ask for a warranty sheet.*

### PACKING & DIMENSIONS

Sheet/Roll Width (± 2%): 6' 7" or 13' 2"  
 Tiles (19.69" x 19.69" ea.): 20 tiles per box (54.18 sq. ft.)

### TECHNICAL SPECIFICATIONS

Dimensional Stability (ASTM D7570-09):	Pass
Electrostatic Propensity (EN 1815):	>2kV
Electrical Resistivity (IBM / ICL):	Pass, for R.H. ≥40%
Sound Insulation (ISO 10140-1:2010):	≥21dB
Thermal Retention (ISO 11092):	0.15 m K/W Pass

### FLAMMABILITY

Radiant Panel (ASTM E648):	Class I
Smoke Density (ASTM E662):	Pass
Surface Flammability (FF 1-70 / ASTM D2859):	Pass
LEED-NC	MR Credit 4   IEQ Credits 4.1, 5

### Maintenance

Regular vacuuming (Weekly in low-traffic areas, and daily or twice daily in areas with higher traffic) with a motor-driven brush and beater bar can remove up to 80% of surface dirt, and is the easiest way to prolong the life of your carpet. Regular vacuuming is key to maintaining your carpet, but eventually the carpet color dulls from dirt and grime stuck in the fibers. The dirt is then carried further into the building to form more soil reservoirs. Additionally, the oil content (15%) of the soil causes particles to stick to carpet fiber and resist vacuuming. To restore the carpet to its best condition, frequent light cleaning gives the best result and is often very cost effective.

\*For more information, plus instructions for stain removal, consult vG's Resource Center at [www.vangelder-inc.com/resources](http://www.vangelder-inc.com/resources)

### IMPORTANT NOTICE

Sample swatches have been cut from an overall design; decoration and shade may vary.

### YOUR AUTHORIZED SALES REPRESENTATIVE:

vG\_Windsor\_RG\_011023



van Gelder, Inc.  
[www.vangelder-inc.com](http://www.vangelder-inc.com)  
 +1 866 284 6287